



Safety

Please take a minute to review the safety information below. We want to make your visit as comfortable as possible. Your safety is of utmost importance. We are looking forward to your visit with us!

1. Always stay with your escort.
2. Required safety equipment: hard hat, safety glasses, hearing protection, leather shoes.
 - Melt shop and scrap yard also require flame retardant jacket and high visibility markings.
3. All jewelry is prohibited except wristwatches, earrings that do not extend below the earlobe, medical alert bracelets, necklaces worn inside the shirt.
 - Note: rings that cannot be removed must be taped over.
4. If an emergency occurs, follow escort to designated assembly area.
5. Miscellaneous:
 - Always stay with your designated Outokumpu escort and follow all verbal and written instructions/requests. Do not leave designated walkways/aisles unless authorized by your escort.
 - When entering and exiting buildings, use pedestrian doors.
 - Use handrails when ascending/descending stairs.
 - Be aware at of the movement of mobile equipment in operational areas. Only proceed past mobile equipment in operation after receiving visual confirmation (i.e., hand signal) by the operator.
 - Never stand or walk under an empty hook and/or a load suspended from a crane. Should an overhead crane or mobile equipment sound a horn, move to the side, and stop. Allow the crane or mobile equipment to pass.
 - Never touch coils or other steel products. They may have sharp edges or be hot to the touch.
 - Strictly adhere to all signage in operational areas.
 - Do not attempt to operate any equipment.
 - Do not enter any confined spaces.
 - If you see any unsafe conditions, please bring to the attention of your escort immediately.
 - Please share any favorable or safe conditions you notice.